



## PHASE THREE


The contractor is responsible for checking dimensions, tolerances and references. Any discrepancy to be verified with the Architect before proceeding with the works. Where an item is covered by drawings to different scales the larger scale drawing is to be worked to.

Do not scale drawing. Figured dimensions to be worked to in all cases.

CDM REGULATIONS 2015. All current drawings and specifications for the project must be read in conjunction with the Designer's Hazard and Environment Assessment Record

All intellectual property rights reserved.

Layouts have been drawn in reference to Building 0-1 Phase 3A Setting Out Plans.



W/DR Combined Washer Dryer

w Washer

Dryer

Room annotations

AFF (above finished floor) - Ceiling height

1 0	21.12.20 13.11.20	Second Issue First Issue	RC RC	AA AA
REV	DATE	DESCRIPTION	BY	CHŁ
Drawing	g Status		<u>'</u>	
		S2 - For Informatio	n	
		A C		
			<del></del>	

PRP

BATTERSEA POWER STATION, PHASE 3A

Drawing Title:
Apartment Type 3B.06.01

Project No Sheet Scale Revision:
C03 (Phase 3) A1 As indicated REV 1

Project-Originator-Zone-Level-Type-Role-Number

C03- PRP- FP1- 06- DRG- AR-0088